

EPA Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

DEPT. OF HEALTH
JUN 22 9 30 PM '85

Site 5

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name THE BENDIX CORPORATION
Street 401 Bendix Drive (P.O. Box 4001)
City South Bend State IN Zip Code 46620

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site "Area West of Bendix Oil Tank"
Street Linden Avenue
City South Bend County St. Joseph State IN Zip Code 46619

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Budzin, Gerald J. - Manager of Environmental Control
Phone (219) 237-5993

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) Intermittently 1940 to 1970 To (Year)

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

May have included:

1. ☒ Organics
2. ☒ Inorganics
3. ☒ Solvents
4. ☐ Pesticides
5. ☒ Heavy metals
6. ☒ Acids
7. ☒ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☐ Unknown
11. ☒ Other (Specify)
Asbestos

Source of Waste:
Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☐ Chemical, General
9. ☒ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☒ Other (Specify)
Automotive/Aerospace
Manufacturing Facility
SIC Code 3714, 3722 &

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located

US EPA RECORDS CENTER REGION 5



447929